

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	6	"6,150,797"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/31 09:13
S2	10	"6,242,893"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/11 12:03
S3	36	battery and (over adj charge or overcharge) near discharge same (shut\$3 or off)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/30 14:38
S4	24	battery and (over adj charge or overcharge) near discharge same (shut\$3 or off)	USPAT	OR	ON	2006/07/30 15:33
S5	0	battery and (over adj charge or overcharge) near discharge same (shut\$3 or off) and kohm	USPAT	OR	ON	2006/07/30 14:50
S6	0	battery and (over adj charge or overcharge) near discharge same (shut\$3 or off) and Kohm	USPAT	OR	ON	2006/07/30 14:50
S7	0	battery and (over adj charge or overcharge) near3 discharge same (shut\$3 or off) and kohm	USPAT	OR	ON	2006/07/30 14:51
S8	0	battery and (over adj charge or overcharge) near5 discharge same (shut\$3 or off) and kohm	USPAT	OR	ON	2006/07/30 14:51
S9	1	battery and (over adj charge or overcharge) near9 discharge same (shut\$3 or off) and kohm	USPAT	OR	ON	2006/07/30 14:59
S10	11	battery and (over adj charge or overcharge) same (shut\$3 or off) and kohm	USPAT	OR	ON	2006/07/30 15:26
S11	0	battery and load near current near (miliamper amper)	USPAT	OR	ON	2006/07/30 15:27
S12	0	battery and load near current near3 (miliamper amper)	USPAT	OR	ON	2006/07/30 15:27
S13	0	battery and load near current near3 (miliamper amper)	USPAT	OR	ON	2006/07/30 15:27

EAST Search History

S14	0	battery and load near3 current near3 (miliamper amper)	USPAT	OR	ON	2006/07/30 15:28
S15	1	battery and load near3 current near9 (miliamper amper)	USPAT	OR	ON	2006/07/30 15:28
S16	0	battery and discharge near resistor near kohm	USPAT	OR	ON	2006/07/30 15:34
S17	1	battery and discharge near resistor near3 kohm	USPAT	OR	ON	2006/07/30 15:35
S18	1	battery and discharge near resistor near5 kohm	USPAT	OR	ON	2006/07/30 15:35
S19	2	battery and discharge near resistor near9 kohm	USPAT	OR	ON	2006/07/30 15:36
S20	7	battery and discharge near3 resistor near9 kohm	USPAT	OR	ON	2006/07/30 15:40
S21	16	battery and discharge near5 resistor near9 kohm	USPAT	OR	ON	2006/07/30 16:10
S22	623	320/134.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/30 16:10
S23	356	320/135.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/31 09:13
S24	618	320/136.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/31 10:26
S25	154	320/118.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/01 16:30